


ALFA 159 1.9 JTD 16V CHECK OF DAMPER CORRECT ORIENTATION 4420AG

Remove the luggage compartment interior lining side panels.

- Carry out op.

Op. 7040B18 LOAD COMPARTMENT LOAD PLATFORM SIDE TRIM ONE LH OR RH - R.R

1. Check that the buffer plate is fitted in the correct position as illustrated in the diagram.



1. If the plate is not fitted in the correct position, refit it correctly as illustrated in the diagram.

